Michael O. Leavitt Governor Robert L. Morgan Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY www.nr.utah.gov

July 17, 2002

Mr. Thomas J. Clark Thomas J. Clark and Company 1145 North 1100 West St. George, Utah 84770

Re:

Site Inspection, Thomas J. Clark and Company, Daddy Dearest Mine, S/015/046, Emery County,

Utah

Dear Mr. Clark:

On June 7, 2002, I visited your mine site in Emery county to investigate some concerns the Bureau of Land Management had after an inspection they made on May 9, 2002. The enclosed inspection report discusses the condition of the site and the problems that need to be corrected. The most pressing issue is that the mine openings need to be properly secured.

Please arrange to have these problems corrected as soon as possible. I anticipate it should be possible to secure the portals within the next 30 days or by August 17, 2002. Please let me know if this schedule is not feasible and how soon you will be able to correct the problems. Although the site may be in noncompliance because of the potential danger to the public, I prefer to work with you to resolve these issues rather than writing a notice of noncompliance.

Please call me at 801-538-5261 if you have any questions about these issues or the work that needs to be done.

Sincerely,

Paul B. Baker

Senior Reclamation Biologist

jb

Enclosure: Inspection report with photos

Enclosure. Inspection report with photo

Val Payne, Emery County Public Lands Council

Tom Rasmussen, Price BLM

Dean Nyffeler, Price BLM

O:\M015-Emery\Clark\final\ltr071702ticlark.doc

